

System Data Sheet



Removing dirt, grime, dust, oil and grease deposits on mineral surfaces with Clean SL

APPLICATION INSTRUCTIONS



1

SUBSTRATE PREPARATION

The surface must be clean, dust-free and dry, and free from damaging salts. Mechanically remove coarse dirt. Wet the surface with water.



3

CLEANING

Use a scrubbing brush to apply the material.



2

CLEANING

Prepare an appropriate concentration of the solution and apply using a suitable device, for example the GLORIA® 410 T Profiline. Depending on the intensity of the contamination, produce a dilution with a concentration of 1:5 - 1:20. Apply to a trial area to assess the cleaning effect.



4

WASHING THE SURFACE

Wash intensively. Remove all traces of the cleaning agent. Repeat the procedure if necessary.

INFO:

The QR code links to the applicable Technical Data Sheet.

Please contact your specialist retailer for more information.

Technical Data Sheet



Products used

SURFACE PROTECTION



Clean SL

Application rate:

Approx. 0.01 - 0.05 l/m² depending on the dirt level. Depending on the intensity of the contamination, produce a dilution with a concentration of 1:5 - 1:20.

Art. No. 0671

TOOLS



GLORIA® 405 / 410 T Profiline

Art. No. 4667