



CASA [24]

CV-BELÄGE


für ein wohnliches Zuhause



CASA [24]

CV-Beläge für ein wohnliches Zuhause

TECHNISCHE DATEN

Bestellnummer	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115
Breite																
2 m			X		X	X	X				X	X	X	X		
4 m	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
PU-versiegelt	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Gesamtdicke (mm) nach DIN EN 428	2,0	2,0	2,0	2,0	2,0	2,8	3,0	2,8	2,8	2,8	2,8	2,8	2,8	2,6	2,8	2,8
Nutzschichtdicke (mm) nach DIN EN 429	0,25	0,25	0,25	0,25	0,25	0,35	0,35	0,4	0,35	0,35	0,35	0,35	0,35	0,20	0,35	0,35
Brandverhalten nach DIN 4107/EN 13501-1 bei vollflächiger Verklebung																
Cfl-s1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
Trittschallverbesserungsmaß nach DIN EN 20717-2 in dB	15	15	15	15	15	19	18	17	19	19	19	19	19	17	19	19
Stuhlrolleneignung / Typ W nach DIN EN 425 vollflächig verklebt						X			X	X	X	X	X		X	X
Klassifizierung/Einsatzbereich nach DIN EN 685																
 22														X		
  23/31	X	X	X	X	X	X	X	X	X	X	X	X	X		X	X
  23/32						X			X	X	X	X	X		X	X
 41						X	X		X	X	X	X	X		X	X
unverb. empf. Preis inkl. gesetzl. MwSt. Euro/m²	16,95 €/m²					19,95 €/m²										
Stand 01.10.2021																

Alle Beläge sind antistatisch ausgerüstet und bei vollflächiger Verklebung fußbodenheizungsg geeignet.
Die Brandschutzklassifizierung Cfl-S1 entspricht der früheren B1-Einstufung.

Bitte vergewissern Sie sich vor der Verlegung, dass Sie die Ware vollständig, gemäß Ihrer Bestellung richtig und im einwandfreien Zustand erhalten haben.
Geringfügige Farbabweichungen sind fabrikationsbedingt, daher kein Grund zur Reklamation. Wir bedauern sehr, dass zugeschnittene Ware nicht zurückgenommen werden kann.




Klassifizierung und Einsatzempfehlung der DIN EN 685




22 = mittlere Beanspruchung im Wohnbereich




23 = starke Beanspruchung im Wohnbereich



31 = mäßige Beanspruchung im gewerblichen Bereich



32 = mittlere Beanspruchung im gewerblichen Bereich



41 = mäßige Beanspruchung im industriellen Bereich

The image features a detailed wood grain texture in shades of brown and tan. The grain runs vertically, with some horizontal lines intersecting it. A dark, curved shape is visible at the bottom of the frame. In the lower-left corner, the text 'CASA [24]' and '100' is displayed in a black, sans-serif font.

CASA [24]
100

The image features a close-up of a wood surface with a vertical grain pattern. The wood has a warm, brownish-tan hue with visible knots and grain variations. A dark, curved shape, possibly a shadow or a design element, is visible along the bottom edge of the frame.

CASA [24]
101

The image features a close-up of a light brown wood surface with a prominent vertical grain. The wood has a natural, slightly weathered appearance with some darker staining and a small knot visible in the lower-middle section. A dark, curved shape, possibly a shadow or a design element, is visible along the bottom edge of the frame.

CASA [24]
102

CASA [24]
103

The image features a close-up of a light brown wood grain texture. The wood grain runs vertically, with some darker, swirling patterns and knots visible. A dark, curved shape, possibly a shadow or a design element, is located at the bottom of the image. The text "CASA [24]" and "104" is overlaid in the bottom left corner.


CASA [24]
104

CASA [24]
105


CASA [24]
106



CASA [24]
107



CASA [24]
108



CASA [24]
109

CASA [24]
110

CASA [24]
111

CASA [24]
112

CASA [24]
113

CASA [24]
114

CASA [24]
115